NOISE Monitoring Data - Monthly Summary			
Month	**Apr-14**		
EPL Licence	**13316**	**Project**	**LTB**
EPL weblink	http://www.environment.nsw.gov.au/prpoeoapp/ViewPOEOLicence.aspx?DOCID=31621&SYSUID=1&LICID=20079		
Specific EPL licence monitoring conditions for noise	**Condition L3 - Noise limits** **Condition E2 - Out of Hours Works**		

Monitoring location	Number of times monitored during the month	Attended or continuous monitoring	Event based monitoring (Y/N)	Parameter eg. Laq (15min)	min value dB(A) for month	max value dB(A) for month	goals / targets dB(A)	Comment
Riverpark Drive (At property boundary facing RiverPark Drive)	NA	NA	NA	NA	NA	NA	NA	No Out of Hours or Local Possession works were conducted during the reporting month near or adjacent to the monitoring receiver.No noise monitoring data provided
Speed St (At property boundary facing speed st)	NA	NA	NA	NA	NA	NA	NA	No Out of Hours or Local Possession works were conducted during the reporting month near or adjacent to the monitoring receiver.No noise monitoring data provided
Liverpool Tafe (At propery boundary facing Moore St near entrance gate)	NA	NA	NA	NA	NA	NA	NA	No Out of Hours or Local Possession works were conducted during the reporting month near or adjacent to the monitoring receiver.No noise monitoring data provided
Liverpool Hospital (At property boundary, Elizabeth St adjacent to beginning of hospital extension)	NA	NA	NA	NA	NA	NA	NA	No Out of Hours or Local Possession works were conducted during the reporting month near or adjacent to the monitoring receiver.No noise monitoring data provided
Manning St (Entrance to old Kimberly Clarke property)	NA	NA	NA	NA	NA	NA	NA	No Out of Hours or Local Possession works were conducted during the reporting month near or adjacent to the monitoring receiver.No noise monitoring data provided
Hart St (New Hospital Road, Eastern boundary fence of Livepool Boys and Girls High School)	NA	NA	NA	NA	NA	NA	NA	No Out of Hours or Local Possession works were conducted during the reporting month near or adjacent to the monitoring receiver.No noise monitoring data provided