Information			Physical Parameters				Metals	
Date	Location	Discharge Location	pH	NTU	Dissolved Oxygen	Visible Oil or Grease	Aluminium	Iron (dissolved)
01/07/2019	Groundwater Extraction - Basin #1	Cess Drain (EPL Discharge Point)	7.97	33.1	8.03	N	1.9	0.61
02/07/2019	Groundwater Extraction - Basin #1	Cess Drain (EPL Discharge Point)	7.92	31.4	12.08	N		
03/07/2019	Groundwater Extraction - Basin #1	Cess Drain (EPL Discharge Point)	8.01	27.3	9.39	N		
04/07/2019	Groundwater Extraction - Basin #1	Cess Drain (EPL Discharge Point)	8.07	28.8	6.09	N		
05/07/2019	Groundwater Extraction - Basin #1	Cess Drain (EPL Discharge Point)	7.82	41.2	6.34	N		
06/07/2019	Groundwater Extraction - Basin #1	Cess Drain (EPL Discharge Point)	7.4	71.7	6.77	N		
07/07/2019	Groundwater Extraction - Basin #1	Cess Drain (EPL Discharge Point)	8.42	72.9	6.11	N		
08/07/2019	Groundwater Extraction - Basin #1	Cess Drain (EPL Discharge Point)	7.68	39.9	7.07	N	<0.05	0.06
09/07/2019	Groundwater Extraction - Basin #1	Cess Drain (EPL Discharge Point)	8.33	56.3	11.48	N		
10/07/2019	Groundwater Extraction - Basin #1	Cess Drain (EPL Discharge Point)	8.22	54.5	11.7	N		
11/07/2019	Groundwater Extraction - Basin #1	Cess Drain (EPL Discharge Point)	8.39	17	11.58	N		
12/07/2019	Groundwater Extraction - Basin #1	Cess Drain (EPL Discharge Point)	8.35	19.4	14.4	N		
13/07/2019	Groundwater Extraction - Basin #1	Cess Drain (EPL Discharge Point)	8.27	13.9	9.36	N		
14/07/2019	Groundwater Extraction - Basin #1	Cess Drain (EPL Discharge Point)	8.01	15.9	12.21	N		
15/07/2019	Groundwater Extraction - Basin #1	Cess Drain (EPL Discharge Point)	8.41	22.6	11.2	N	<0.05	0.09
16/07/2019	Groundwater Extraction - Basin #1	Cess Drain (EPL Discharge Point)	8.22	16.8	9.98	N		
17/07/2019	Groundwater Extraction - Basin #1	Cess Drain (EPL Discharge Point)	8.46	90.5	9.58	N		