

**NOISE Monitoring Data - Monthly Summary**

Month	<b>Sep-18</b>		
EPL Licence	<b>20851</b>	Project	<b>Westconnex Enabling - Airport East Precinct</b>
EPL weblink	<a href="http://www.epa.nsw.gov.au/prpoeoapp/ViewPOEOLicence.aspx?DOCID=110002&amp;SYSUID=1&amp;LICID=20851">http://www.epa.nsw.gov.au/prpoeoapp/ViewPOEOLicence.aspx?DOCID=110002&amp;SYSUID=1&amp;LICID=20851</a>		
Specific EPL licence monitoring conditions for noise	<b>Condition L2 - Noise limits</b>		<b>Condition L3 - Out of Hours Works</b>

Monitoring location	Number of times monitored during the month	Attended or continuous monitoring	Event based monitoring (Y/N)	Parameter eg. Laq (15min)	Min value dB(A) for month	Max value dB(A) for month	Goals / targets dB(A)	Observations
1 Wentworth Avenue	4	Attended	Y	Leq	66.1	76.1	81	<p><b>Observations</b></p> <p>Saw cutting of Asphalt trench, excavation works and drainage works</p> <p>Sheet piling works on the western side of rail bridge were intermittently audible</p> <p>Dominant noise source from continuous road traffic.</p> <p>Alternative accommodation was offered during the period of works.</p> <p>No community noise complaint received.</p>
5 Ross Smith Avenue (IBIS Hotel)	2	Attended	Y	Leq	73	74.9	74	<p><b>Observations</b></p> <p>Placing of Asphalt, use of roller, milling machine and compactor</p> <p>Non-construction noise source that were audible during monitoring period was road traffic.</p> <p>Construction works were intermittently audible during monitoring events.</p> <p>No community noise complaint received.</p>
1295 Botany Road	1	Attended	Y	Leq	68.4	68.4	75	<p><b>Observations</b></p> <p>Excavation works along Wentworth Avenue using excavator, backhoe, truck and compactor</p> <p>General housekeeping works within the Wentworth Compound</p> <p>Works were predominantly inaudible with dominant noise source from road traffic.</p> <p>No community noise complaint received.</p>
1299 Botany Road	2	Attended	Y	Leq	64.3	65.8	75	<p><b>Observations</b></p> <p>Excavation works at the intersection of Botany Road and Wentworth Avenue using excavator, backhoe, truck and compactor</p> <p>Sheet piling works on the western side of rail bridge were intermittently audible</p> <p>Works were predominantly inaudible</p> <p>No community noise complaint received</p>