

**NOISE Monitoring Data - Monthly Summary**

Month	March 2019		
EPL Licence	20851	Project	Westconnex Enabling - Airport East Precinct
EPL weblink	<a href="http://www.epa.nsw.gov.au/prpoeoapp/ViewPOEOLicence.aspx?DOCID=110002&amp;SYSUID=1&amp;LICID=20851">http://www.epa.nsw.gov.au/prpoeoapp/ViewPOEOLicence.aspx?DOCID=110002&amp;SYSUID=1&amp;LICID=20851</a>		
Specific EPL licence monitoring conditions for noise	Condition L2 - Noise limits		Condition L3 - Out of Hours Works

Monitoring location	Number of times monitored during the month	Attended or continuous monitoring	Event based monitoring (Y/N)	Parameter eg. Laq (15min)	Min value dB(A) for month	Max value dB(A) for month	Goals / targets dB(A)	Observations / Comments
1297 Botany Road	7	Attended	Y	Leq	62.8	69.2	77	Sheet piling, screw piling, jackhammering, steel fixing and concrete works at the underpass Craneage moving materials east side of the rail bridge were inaudible. Cut and Replacing water main pipes were intermittently audible. Alternative accommodation was offered during the period of works. Continuous road traffic - audible No community noise complaint received
87 Hardie Street	1	Attended	Y	Leq	66.2	66.2	73	Placement of DGB at Wentworth Compound footpath Alternative accommodation was offered during the period of works. Continuous road traffic - audible No community noise complaint received
1 Wentworth Ave	1	Attended	Y	Leq	62.4	62.4	71	TSC works - excavation and loading trucks Alternative accommodation was offered during the period of works. Continuous road traffic - audible No community noise complaint received
1281 Botany Road	1	Attended	Y	Leq	69.8	69.8	66	Investigation works for tram tracks were intermittently audible. Jackhammering and hand drilling were intermittently audible. Traffic along Botany Road generated dominant noise Alternative accomodation offered to relevant residents for these works No community noise complaint received